| | CLASS | TYPE OF EQUIPMENT | ESTIMATED DEF | ERRED |
|---------------|------------------------------------|--|---------------|-----------|
| FACILITY NAME | | | MAINTENANCE | COST |
| WEST GATE ES | BUILDING ENVELOPE | | \$ | 595,920 |
| | | Exterior Doors | | |
| | | Exterior Finishes (i.e., Stucco) | | |
| | | Gutters & Downspouts | | |
| | | Modulars-BEMP (i.e., Roof, Windows, D | Doors) | |
| | | Water Intrusion/Waterproof Application | n | |
| | COMPLIANCE | | \$ | 509,698 |
| | | ADA Violations | | • |
| | | CSIR Violations | | |
| | CUSTODIAL EQUIPMENT | | \$ | 24,128 |
| | | Custodial Equipment-Replacement | * | ,0 |
| | FENCING | Custodiai Equipment Replacement | \$ | 117,000 |
| | LINCHING | Perimeter Fencing | 7 | 117,000 |
| | FIRE /LIFE /CAFFTV | Perimeter Fencing | <u></u> | 175 665 |
| | FIRE/LIFE/SAFETY | Since Alleger / Device I Harmonda | \$ | 175,665 |
| | | Fire Alarm/Panel Upgrade | In comment | |
| | | Fire Alarm/Smoke & Duct Detector Rep | | |
| | FURNITURE & EQUIPMENT | | \$ | 223,236 |
| | | Classroom Furniture | | |
| | HVAC | | \$ | 200,800 |
| | | Modulars-HVAC | | |
| | | Sheet Metal-Ductwork/Outside Air Dan | npers | |
| | INTERIOR REPAIRS & IMPROVEMENTS | | \$ | 939,481 |
| | | Acoustical Ceiling | | |
| | | Flooring Vinyl | | |
| | PARKING LOT | | \$ | 353,653 |
| | | Parking Lot Paving/Striping | | |
| | PLAYFIELDS & EXTERIOR REPAIRS & IM | | \$ | 55,000 |
| | | Play Courts | · | ŕ |
| | | Playground Surfacing PIP (Rubber)/Re-Cap Attenuating Surfacing | | |
| | PLUMBING | ,8 | \$ | 63,750 |
| | | Boilers - Kitchen Replacement (2) | • | 00,.00 |
| | | Plumbing-Water Fountains | | |
| | ROOFS | i idinamg-water i duntama | \$ | 10,400 |
| | NOOF3 | Roof Ronaire | ş | 10,400 |
| Grand Total | | Roof Repairs | \$ | 3,268,732 |